



HNE800H

MCCBs h1000 3 pole 50 kA

Description	P.U.	Cat ref.
MCCB h1000 3P 50kA 800A LSI	1	HNE800H
MCCB h1000 3P 50kA 1000A LSI	1	HNE970H



HNE801H

MCCBs h1000 4 pole 50 kA

Description	P.U.	Cat ref.
MCCB h1000 4P 50kA 800A LSI	1	HNE801H
MCCB h1000 4P 50kA 1000A LSI	1	HNE971H



HEE800H

MCCBs h1000 3 pole 70 kA

Description	P.U.	Cat ref.
MCCB h1000 3P 70kA 800A LSI	1	HEE800H
MCCB h1000 3P 70kA 1000A LSI	1	HEE970H



HEE801H

MCCBs h1000 4 pole 70 kA

Description	P.U.	Cat ref.
MCCB h1000 4P 70kA 800A LSI	1	HEE801H
MCCB h1000 4P 70kA 1000A LSI	1	HEE971H



HCE970H

Switch disconnectors h1000 3 pole

Description	P.U.	Cat ref.
Switch h1000 3P 1000A	1	HCE970H